

DiMAX 100A : PC-Modul (8175001)

Version	Stand / Änderungen	Datum	Nötiges Zubehör
1.0	1.Serie (MZS-III + Busgeräte updaten , Eigenupdate)	16.10.06	
Hardw.	Geänderte Platine für Dekoder-Programmierung	13.03.07	
1.5	CV Programmieren + Auslesen von Dekodern	04.03.08	
2.0	Update + Soundprogrammierung von Massoth-Dekodern	20.03.08	<i>Dekoder ab V2.0</i>
2.1	Update von DiMAX Multifunkempfängern (XpressNet+LocoNet)	03.06.08	
2.2	Optimierung CV-Prog , Optimierte Fehlercodes	06.10.09	

Das Gerät kann selbst auf den aktuellen Softwarestand gebracht werden.

DiMAX 100A : PC-Module (8175001)

Version	revision / changes	date	required accessories
1.0	1.series (MTS-III + update bus devices, self update)	10/16/06	
Hardw.	Changed PCB for decoder programming	03/13/07	
1.5	CV programming + readout of decoders	03/04/08	
2.0	Update + soundprogramming of Massoth-decoder	03/20/08	<i>Decoder from V2.0</i>
2.1	Update of DiMAX Multi RC receiver (XpressNet+LocoNet)	06/03/08	

The device could be programmed by oneself to the newest firmware release.