

82930xx-Melody

Version	revision / changes	date
2.0	Random generator implemented	18/09/24
2.1	Random generator switched with function key 13	18/12/13
2.2	Troubleshooting Buffer Connection	17/03/21

The decoder could be programmed by oneself to the newest firmware release.
Delivery of melody started on version 1.0